

4-1242-BGS-T055  
Friday, April 6, 1990


To:	C. Cherberg	R-6570	63-01
cc:	Y. Barnett	R-6570	63-01
	T. Frees	R-6201	93-03
	J. Johnston	4-3112	99-05
	J. Medzegan	4-1200	6U-24
	D. Smukowski	4-1242	6U-02
	K. Thomson	4-1240	6U-02
	J. Wooten	B-Z608	73-43
	V. J. Vinson	4-1200	6U-04

Subject: Spill Eastside 10-71 bldg. 4/5/90 1745 hours.

At 1755 hours a call was received from Renton Fire dispatch that a spill of Chromic acid, Nitric acid, and Hydrofluoric acid waste had occurred outside of the 10-71 bldg. on the eastside. There was estimated to be from 5 to 10 gallons of material spilled.

I arrived at the scene at 1810 hours. The Renton HazMat team had not responded yet. Due to the size of the spill, my familiarity with the chemicals, my certification as Hazardous Materials Technician Level, and the approach of darkness, it was decided that I would enter the incident with two Renton Firefighters for spill control. The Renton HazMat team when they arrived would be used for cleanup and for a possible second incident at the 4-42 bldg.

Entry was made at about 1900 hours. Material in the area was removed by the firefighters, then the spill was neutralized using Ansul Spill-X A. Spill control was completed by 1935 hours and the incident scene was returned to the Renton facilities team. The 4-42 bldg. was investigated and the spill was declared as non-hazardous and was cleaned up.



Prepared by: B. Gary Scherck  
BSS Emergency Response 4-1242 M/S 9A-26